

Flr	Location	Samp#	Description	Code	N.D.	Pos	Quan	Unit	Fri	Cond	Rate	Samp Date	Survey	Amos	Chrys	Croc	Trem	Actin	Anth	Project #
B	Hall	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/9/98	Goar/Nova							040-94-051
B	Hall	45	12"x12" pegboard CT	M	ND		693	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Hall	45.5	ceiling tile adhesive (sample 45)	M		Pos	693	SF	N	N	1	5/9/98	Goar/Nova		15%					040-94-051
B	Hall	R1	<4" white fibrous PI (3/27/90)	T		Pos	20	LF	F	N	2	5/8/94	Goar/Nova		30%					040-94-051
B	Hall	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		30%			1%		040-94-051
B	Hall	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Hall	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Interstitial Sp	27	clay tile mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Interstitial Sp	28	yellow brick mortar	M	ND			SF	N	N	0	5/8/94	Goar/Nova							040-94-051
B	Interstitial Sp	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	10	LF	F	L	3	5/8/94	Goar/Nova	25%	15%					040-94-051
B	Interstitial Sp	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	2	EA	F	L	3	5/8/94	Goar/Nova	16%	12%					040-94-051
B	Interstitial Sp	R3	<4"aircell PI (6/27/90)	T		Pos	90	LF	F	L	3	5/8/94	Goar/Nova		75%					040-94-051
B	Interstitial Sp	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	2	EA	F	L	3	5/8/94	Goar/Nova		1%			2%		040-94-051
B	Interstitial Sp	R5	<4" felt with tar PI (12/7/90)	T		Pos	250	LF	F	N	2	5/8/94	Goar/Nova		21%					040-94-051
B	Interstitial Sp	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	3	EA	F	L	3	5/8/94	Goar/Nova		65%					040-94-051
B	Room 01	R1	<4" white fibrous PI (3/27/90)	T		Pos	80	LF	F	L	3	5/8/94	Goar/Nova		30%					040-94-051
B	Room 01	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	50	LF	F	L	3	5/8/94	Goar/Nova	25%	15%					040-94-051
B	Room 01	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	13	EA	F	L	3	5/8/94	Goar/Nova	16%	12%					040-94-051
B	Room 01	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	28	EA	F	N	2	5/8/94	Goar/Nova		30%			1%		040-94-051
B	Room 01	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 01	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 01	R5	<4" felt with tar PI (12/7/90)	T		Pos	120	LF	F	L	3	5/8/94	Goar/Nova		21%					040-94-051
B	Room 01	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	35	EA	F	L	3	5/8/94	Goar/Nova		65%					040-94-051
B	Room 02	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 02	31	9"x9" light grey marble FT	M		Pos	320	SF	N	N	1	5/8/94	Goar/Nova		5%					040-94-051
B	Room 02	31.5	floor tile adhesive (sample 31)	M		Pos	320	SF	N	N	1	5/8/94	Goar/Nova		5%					040-94-051
B	Room 02	45	12"x12" pegboard CT	M	ND		480	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 02	45.5	ceiling tile adhesive (sample 45)	M		Pos	480	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
B	Room 02	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 02	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 02	R5	<4" felt with tar PI (12/7/90)	T		Pos	13	LF	F	N	2	5/8/94	Goar/Nova		21%					040-94-051
B	Room 02	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	3	EA	F	N	2	5/8/94	Goar/Nova		65%					040-94-051

B	Room 03	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 03	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 03	37	12"x12" beige w/brown molting FT	M	ND		244	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 03	37.5	floor tile adhesive (sample 37)	M	ND		244	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 03	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 03	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 04	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 04	34	9"x9" light grey w/white & charcoal F	M		Pos	1000	SF	N	N	1	5/8/94	Goar/Nova		5%				040-94-051
B	Room 04	34.5	floor tile adhesive (sample 31)	M	ND		1000	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 04	38	2'x4' fissured CT	M	ND		980	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 04	45	12"x12" pegboard CT	M	ND		1000	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 04	45.5	ceiling tile adhesive (sample 45)	M		Pos	1000	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
B	Room 04	R1	<4" white fibrous PI (3/27/90)	T		Pos	90	LF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 04	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	84	LF	F	N	2	5/8/94	Goar/Nova	25%	15%				040-94-051
B	Room 04	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	6	EA	F	N	2	5/8/94	Goar/Nova	16%	12%				040-94-051
B	Room 04	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	16	EA	F	N	2	5/8/94	Goar/Nova		30%			1%	040-94-051
B	Room 04	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 04	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 05(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	14	LF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 05(tre	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	12	LF	F	N	2	5/8/94	Goar/Nova	25%	15%				040-94-051
B	Room 05(tre	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova	16%	12%				040-94-051
B	Room 05(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	13	EA	F	N	2	5/8/94	Goar/Nova		30%			1%	040-94-051
B	Room 05	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 05	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 06(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	8	LF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 06(tre	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	9	LF	F	N	2	5/8/94	Goar/Nova	25%	15%				040-94-051
B	Room 06(tre	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova	16%	12%				040-94-051
B	Room 06(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	8	EA	F	L	3	5/8/94	Goar/Nova		30%			1%	040-94-051
B	Room 06	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 06	49	white fibrous debris	M		Pos		SF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 06	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 06	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

B	Room 07	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 07	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 07	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 08	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 08	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 08	46	2'x2' fissured CT	M	ND		480	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 08	R1	<4" white fibrous PI (3/27/90)	T		Pos	8	LF	F	N	2	5/8/94	Goar/Nova							040-94-051
B	Room 08	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	11	LF	F	N	2	5/8/94	Goar/Nova	25%						040-94-051
B	Room 08	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova	16%						040-94-051
B	Room 08	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 08	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	27	clay tile mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	50	canvass vibration joint	M	ND		4	EA	N	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	62	<4" fibrous PFI on foam	T		Pos	18	EA	F	N	2	5/8/94	Goar/Nova	3%						040-94-051
B	Room 09	R1	<4" white fibrous PI (3/27/90)	T		Pos	180	LF	F	L	3	5/8/94	Goar/Nova							040-94-051
B	Room 09	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	85	LF	F	N	2	5/8/94	Goar/Nova	25%						040-94-051
B	Room 09	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	12	EA	F	L	3	5/8/94	Goar/Nova	16%						040-94-051
B	Room 09	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	92	EA	F	N	2	5/8/94	Goar/Nova							040-94-051
B	Room 09	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	R3	<4"aircell PI (6/27/90)	T		Pos	25	LF	F	L	3	5/8/94	Goar/Nova							040-94-051
B	Room 09	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	3	EA	F	N	2	5/8/94	Goar/Nova							040-94-051
B	Room 09	R5	<4" felt with tar PI (12/7/90)	T		Pos	8	LF	F	N	2	5/8/94	Goar/Nova							040-94-051
B	Room 09	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova							040-94-051
B	Room 09	R61	fiberglass duct insulation (12/11/90)	M	ND			SF	N	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	8	EA	F	N	2	5/8/94	Goar/Nova							040-94-051
B	Room 09A	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09A	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 09A	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 10	45	12"x12" pegboard CT	M	ND		230	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
B	Room 10	45.5	ceiling tile adhesive (sample 45)	M		Pos	230	SF	N	N	1	5/8/94	Goar/Nova							040-94-051

B	Room 10	R1	<4" white fibrous PI (3/27/90)	T		Pos	1	LF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 10	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 10	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 10	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 10	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
B	Room 11	R1	<4" white fibrous PI (3/27/90)	T		Pos	12	LF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 11	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	6	LF	F	N	2	5/8/94	Goar/Nova	25%	15%				040-94-051
B	Room 11	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova	16%	12%				040-94-051
B	Room 11	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	4	EA	F	N	2	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 11	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 11	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 11	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
B	Room 12	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 12	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 13	45	12"x12" pegboard CT	M	ND		288	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 13	45.5	ceiling tile adhesive (sample 45)	M		Pos	288	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
B	Room 13	R1	<4" white fibrous PI (3/27/90)	T		Pos	36	LF	F	M	4	5/8/94	Goar/Nova		30%				040-94-051
B	Room 13	R10	4"-8" white fibrous PI (12/7/90)	T		Pos	18	LF	F	M	4	5/8/94	Goar/Nova	25%	15%				040-94-051
B	Room 13	R11	4"-8" PFI on white fibrous (12/7/90)	T		Pos	3	EA	F	M	4	5/8/94	Goar/Nova	16%	12%				040-94-051
B	Room 13	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	13	EA	F	M	4	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 13	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 13	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 13	R3	<4"aircell PI (6/27/90)	T		Pos	12	LF	F	M	4	5/8/94	Goar/Nova		75%				040-94-051
B	Room 13	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	6	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
B	Room 14(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	27	LF	F	M	4	5/8/94	Goar/Nova		30%				040-94-051
B	Room 14(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	5	EA	F	M	4	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 14(tre	R3	<4"aircell PI (6/27/90)	T		Pos	12	LF	F	M	4	5/8/94	Goar/Nova		75%				040-94-051
B	Room 14	27	clay tile mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 14	50	canvass vibration joint	M	ND		1	EA	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 14	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 14	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

B	Room 14A	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 14A	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 15	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 15	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 16	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 16	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 16	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	32	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
B	Room 17	27	clay tile mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 17	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 17	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 18	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 18	35	12"x12" white w/tan FT	M		Pos	160	SF	N	N	1	5/8/94	Goar/Nova		10%				040-94-051
B	Room 18	35.5	floor tile adhesive (sample 35)	M		Pos	160	SF	N	N	1	5/8/94	Goar/Nova		3%				040-94-051
B	Room 18	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 18	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 19	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 19	46	2'x2' fissured CT	M	ND		960	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 19	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 19	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 20	42	green and black linoleum	M	ND		260	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 20	43	green linoleum	M	ND		26	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 20	R1	<4" white fibrous PI (3/27/90)	T		Pos	60	LF	F	L	3	5/8/94	Goar/Nova		30%				040-94-051
B	Room 20	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	17	EA	F	L	3	5/8/94	Goar/Nova		30%			1%	040-94-051
B	Room 20	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 20	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 21	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 21	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 21	R3	<4"aircell PI (6/27/90)	T		Pos	8	LF	F	N	2	5/8/94	Goar/Nova		75%				040-94-051
B	Room 21	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		1%			2%	040-94-051

B	Room 22(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	28	LF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 22(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	8	EA	F	N	2	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 22	39	gasket	M	ND			SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 22	53	hard black duct	M	ND		2	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 22	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 22	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 22	R3	<4"aircell PI (6/27/90)	T		Pos	6	LF	F	M	4	5/8/94	Goar/Nova		75%				040-94-051
B	Room 22	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		1%		2%		040-94-051
B	Room 23(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	48	LF	F	M	4	5/8/94	Goar/Nova		30%				040-94-051
B	Room 23(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	13	EA	F	M	4	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 23(tre	R3	<4"aircell PI (6/27/90)	T		Pos	15	LF	F	M	4	5/8/94	Goar/Nova		75%				040-94-051
B	Room 23	54	black table top	M	ND		40	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 23	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 23	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 23	R5	<4" felt with tar PI (12/7/90)	T		Pos	14	LF	F	N	2	5/8/94	Goar/Nova		21%				040-94-051
B	Room 23	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	4	EA	F	N	2	5/8/94	Goar/Nova		65%				040-94-051
B	Room 23	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	6	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
B	Room 24(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	65	LF	F	L	3	5/8/94	Goar/Nova		30%				040-94-051
B	Room 24(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	11	EA	F	L	3	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 24(tre	R3	<4"aircell PI (6/27/90)	T		Pos	23	LF	F	L	3	5/8/94	Goar/Nova		75%				040-94-051
B	Room 24	49	white fibrous debris	M		Pos		SF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 24	59	light padding	M		Pos	36	SF	F	N	2	5/8/94	Goar/Nova		95%				040-94-051
B	Room 24	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 24	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 24	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	4	EA	F	L	3	5/8/94	Goar/Nova		5%				040-94-051
B	Room 25(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	32	LF	F	L	3	5/8/94	Goar/Nova		30%				040-94-051
B	Room 25(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	3	EA	F	M	4	5/8/94	Goar/Nova		30%		1%		040-94-051
B	Room 25(tre	R3	<4"aircell PI (6/27/90)	T		Pos	10	LF	F	L	3	5/8/94	Goar/Nova		75%				040-94-051
B	Room 25	49	white fibrous debris	M		Pos		SF	F	N	2	5/8/94	Goar/Nova		30%				040-94-051
B	Room 25	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

B	Room 25	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 26	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 26	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 26	R3	<4"aircell PI (6/27/90)	T		Pos	24	LF	F	N	2	5/8/94	Goar/Nova	75%					040-94-051
B	Room 26	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	6	EA	F	N	2	5/8/94	Goar/Nova	1%			2%		040-94-051
B	Room 27(tre	R1	<4" white fibrous PI (3/27/90)	T		Pos	22	LF	F	L	3	5/8/94	Goar/Nova	30%					040-94-051
B	Room 27(tre	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	6	EA	F	L	3	5/8/94	Goar/Nova	30%			1%		040-94-051
B	Room 27(tre	R3	<4"aircell PI (6/27/90)	T		Pos	9	LF	F	L	3	5/8/94	Goar/Nova	75%					040-94-051
B	Room 27	18	4"-8" fibrous PFI on FG	T	ND		3	EA	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 27	49	white fibrous debris	M		Pos		SF	F	N	2	5/8/94	Goar/Nova	30%					040-94-051
B	Room 27	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 27	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 27	R5	<4" felt with tar PI (12/7/90)	T		Pos	10	LF	F	L	3	5/8/94	Goar/Nova	21%					040-94-051
B	Room 27	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	1	EA	F	L	3	5/8/94	Goar/Nova	65%					040-94-051
B	Room 27	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	16	EA	F	L	3	5/8/94	Goar/Nova	5%					040-94-051
B	Room 29	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
B	Room 29	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Attic Stair	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Attic Stair	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Center Stair	R1	<4" white fibrous PI (3/27/90)	T		Pos	14	LF	F	N	2	5/8/94	Goar/Nova	30%					040-94-051
	Center Stair	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	3	EA	F	N	2	5/8/94	Goar/Nova	30%			1%		040-94-051
	Center Stair	R3	<4"aircell PI (6/27/90)	T		Pos	42	LF	F	N	2	5/8/94	Goar/Nova	75%					040-94-051
	Center Stair	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	4	EA	F	N	2	5/8/94	Goar/Nova	1%			2%		040-94-051
	Center Stair	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Center Stair	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Elevator Sha	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Elevator Sha	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
	Exterior	26	red brick mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

	North Stair	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051	
	North Stair	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
	SE Stair	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
	SE Stair	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
	Theatre Stai	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
	Theatre Stai	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Hall	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Hall	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Hall	45	12"x12" pegboard CT	M	ND		160	SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Hall	45.5	ceiling tile adhesive (sample 45)	M		Pos	160	SF	N	N	1	5/8/94	Goar/Nova		15%						040-94-051
1	Hall	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Hall	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Lobby	45	12"x12" pegboard CT	M	ND		750	SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Lobby	45.5	ceiling tile adhesive (sample 45)	M		Pos	750	SF	N	N	1	5/8/94	Goar/Nova		15%						040-94-051
1	Lobby	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Lobby	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 101	45	12"x12" pegboard CT	M	ND		72	SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 101	45.5	ceiling tile adhesive (sample 45)	M		Pos	72	SF	N	N	1	5/8/94	Goar/Nova		15%						040-94-051
1	Room 101	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 101	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 101	R5	<4" felt with tar PI (12/7/90)	T		Pos	18	LF	F	L	3	5/8/94	Goar/Nova		21%						040-94-051
1	Room 102	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 102	36	12"x12" tan w/white FT	M		Pos	350	SF	N	N	1	5/8/94	Goar/Nova		2%						040-94-051
1	Room 102	36.5	floor tile adhesive (sample 36)	M		Pos	350	SF	N	N	1	5/8/94	Goar/Nova		7%						040-94-051
1	Room 102	45	12"x12" pegboard CT	M	ND		350	SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 102	45.5	ceiling tile adhesive (sample 45)	M		Pos	350	SF	N	N	1	5/8/94	Goar/Nova		15%						040-94-051
1	Room 102	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 102	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051
1	Room 103	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova								040-94-051

1	Room 103	37	12"x12" beige w/brown molting FT	M	ND		256	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 103	37.5	floor tile adhesive (sample 37)	M	ND		256	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 103	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104	36	12"x12" tan w/white FT	M		Pos	250	SF	N	N	1	5/8/94	Goar/Nova					2%	040-94-051
1	Room 104	36.5	floor tile adhesive (sample 36)	M		Pos	250	SF	N	N	1	5/8/94	Goar/Nova					7%	040-94-051
1	Room 104	45	12"x12" pegboard CT	M	ND		315	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104	45.5	ceiling tile adhesive (sample 45)	M		Pos	315	SF	N	N	1	5/8/94	Goar/Nova					15%	040-94-051
1	Room 104	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104A	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104A	36	12"x12" tan w/white FT	M		Pos	280	SF	N	N	1	5/8/94	Goar/Nova					2%	040-94-051
1	Room 104A	36.5	floor tile adhesive (sample 36)	M		Pos	280	SF	N	N	1	5/8/94	Goar/Nova					7%	040-94-051
1	Room 104A	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104A	45	12"x12" pegboard CT	M	ND		200	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104A	45.5	ceiling tile adhesive (sample 45)	M		Pos	200	SF	N	N	1	5/8/94	Goar/Nova					15%	040-94-051
1	Room 104A	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104A	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104B	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104B	36	12"x12" tan w/white FT	M		Pos	110	SF	N	N	1	5/8/94	Goar/Nova					2%	040-94-051
1	Room 104B	36.5	floor tile adhesive (sample 36)	M		Pos	110	SF	N	N	1	5/8/94	Goar/Nova					7%	040-94-051
1	Room 104B	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104B	45	12"x12" pegboard CT	M	ND		90	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104B	45.5	ceiling tile adhesive (sample 45)	M		Pos	90	SF	N	N	1	5/8/94	Goar/Nova					15%	040-94-051
1	Room 104B	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104B	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104C	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104C	36	12"x12" tan w/white FT	M		Pos	110	SF	N	N	1	5/8/94	Goar/Nova					2%	040-94-051
1	Room 104C	36.5	floor tile adhesive (sample 36)	M		Pos	110	SF	N	N	1	5/8/94	Goar/Nova					7%	040-94-051
1	Room 104C	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104C	45	12"x12" pegboard CT	M	ND		90	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104C	45.5	ceiling tile adhesive (sample 45)	M		Pos	90	SF	N	N	1	5/8/94	Goar/Nova					15%	040-94-051
1	Room 104C	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

1	Room 104C	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104D	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104D	36	12"x12" tan w/white FT	M		Pos	180	SF	N	N	1	5/8/94	Goar/Nova		2%				040-94-051
1	Room 104D	36.5	floor tile adhesive (sample 36)	M		Pos	180	SF	N	N	1	5/8/94	Goar/Nova		7%				040-94-051
1	Room 104D	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104D	45	12"x12" pegboard CT	M	ND		210	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104D	45.5	ceiling tile adhesive (sample 45)	M		Pos	210	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
1	Room 104D	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104D	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104E	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104E	36	12"x12" tan w/white FT	M		Pos	96	SF	N	N	1	5/8/94	Goar/Nova		2%				040-94-051
1	Room 104E	36.5	floor tile adhesive (sample 36)	M		Pos	96	SF	N	N	1	5/8/94	Goar/Nova		7%				040-94-051
1	Room 104E	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104E	45	12"x12" pegboard CT	M	ND		150	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104E	45.5	ceiling tile adhesive (sample 45)	M		Pos	150	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
1	Room 104E	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 104E	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 105	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 105	36	12"x12" tan w/white FT	M		Pos	360	SF	N	N	1	5/8/94	Goar/Nova		2%				040-94-051
1	Room 105	36.5	floor tile adhesive (sample 36)	M		Pos	360	SF	N	N	1	5/8/94	Goar/Nova		7%				040-94-051
1	Room 105	45	12"x12" pegboard CT	M	ND		360	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 105	45.5	ceiling tile adhesive (sample 45)	M		Pos	360	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
1	Room 105	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 105	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 107	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 107	36	12"x12" tan w/white FT	M		Pos	216	SF	N	N	1	5/8/94	Goar/Nova		2%				040-94-051
1	Room 107	36.5	floor tile adhesive (sample 36)	M		Pos	216	SF	N	N	1	5/8/94	Goar/Nova		7%				040-94-051
1	Room 107	45	12"x12" pegboard CT	M	ND		216	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 107	45.5	ceiling tile adhesive (sample 45)	M		Pos	216	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
1	Room 107	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 107	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

1	Room 108	52	transite (assumed)	M		Pos	500	SF	N	N	1	5/8/94	Goar/Nova						040-94-051
1	Room 108	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	27	clay tile mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	28	yellow brick mortar	M	ND			SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	58	electrical wrap	M	ND		10	LF	N	N	1	5/8/94	Goar/Nova						040-94-051
1	Room 108A	R3	<4"aircell PI (6/27/90)	T		Pos	30	LF	F	L	3	5/8/94	Goar/Nova		75%				040-94-051
1	Room 108A	28	yellow brick mortar	M	ND			SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	44	brown linoleum	M	ND		200	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	55	fire curtain	M		Pos	1	EA	N	N	1	5/8/94	Goar/Nova		75%				040-94-051
1	Room 108A	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108A	R3	<4"aircell PI (6/27/90)	T		Pos	24	LF	F	L	3	5/8/94	Goar/Nova		75%				040-94-051
1	Room 108A	R4	<4" fibrous PFI on aircell (6/27/90)	T		Pos	1	EA	F	L	3	5/8/94	Goar/Nova		1%		2%		040-94-051
1	Room 108A	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	4	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
1	Room 108B	57	asbestos wiring	M		Pos	10	LF	N	N	1	5/8/94	Goar/Nova		55%				040-94-051
1	Room 108B	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108B	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 108C	32	9"x9" dark grey FT	M		Pos	45	SF	N	N	1	5/8/94	Goar/Nova		10%				040-94-051
1	Room 108C	32.5	floor tile adhesive (sample 32)	M		Pos	45	SF	N	N	1	5/8/94	Goar/Nova		4%				040-94-051
1	Room 108C	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 109	60	9"x9" light grey w/black & grey FT	M		Pos	216	SF	N	N	0	5/8/94	Goar/Nova		10%				040-94-051
1	Room 109	60.5	floor tile adhesive (sample 60)	M	ND		216	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 109	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 109	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 110	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 110	32	9"x9" dark grey FT	M		Pos	50	SF	N	N	1	5/8/94	Goar/Nova		10%				040-94-051
1	Room 110	32.5	floor tile adhesive (sample 32)	M		Pos	50	SF	N	N	1	5/8/94	Goar/Nova		4%				040-94-051
1	Room 110	35	12"x12" white w/tan FT	M		Pos	1	SF	N	N	1	5/8/94	Goar/Nova		10%				040-94-051
1	Room 110	35.5	floor tile adhesive (sample 35)	M		Pos	1	SF	N	N	1	5/8/94	Goar/Nova		3%				040-94-051
1	Room 110	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

1	Room 110	45	12"x12" pegboard CT	M	ND		72	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 110	45.5	ceiling tile adhesive (sample 45)	M		Pos	72	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
1	Room 110	48	gray linoleum	M	ND		70	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 110	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room 110	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room M 108	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	Room M 108	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	SE Entry	R1	<4" white fibrous PI (3/27/90)	T		Pos	1	LF	F	L	3	5/8/94	Goar/Nova		30%				040-94-051
1	SE Entry	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		30%		1%		040-94-051
1	SE Entry	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
1	SE Entry	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Corridor	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Corridor	44	brown linoleum	M	ND		5603	SF	N	N	0	5/8/94	Goar/Nova						040-94-051
2	Corridor	45	12"x12" pegboard CT	M	ND		621	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Corridor	45.5	ceiling tile adhesive (sample 45)	M		Pos	621	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Corridor	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Corridor	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Hall	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Hall	45	12"x12" pegboard CT	M	ND		204	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Hall	45.5	ceiling tile adhesive (sample 45)	M		Pos	204	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Hall	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Hall	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 201	41	textured plaster	M		Pos	350	SF	F	N	2	5/8/94	Goar/Nova		2%				040-94-051
2	Room 201	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 201	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 201	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	11	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
2	Room 202	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 202	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 202	R5	<4" felt with tar PI (12/7/90)	T		Pos	16	LF	F	N	2	5/8/94	Goar/Nova		21%				040-94-051
2	Room 202	R6	<4" fibrous PFI on felt (12/7/90)	T		Pos	4	EA	F	N	2	5/8/94	Goar/Nova		65%				040-94-051

2	Room 203	45	12"x12" pegboard CT	M	ND		176	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 203	45.5	ceiling tile adhesive (sample 45)	M		Pos	176	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 203	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 203	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 204	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 204	36	12"x12" tan w/white FT	M		Pos	234	SF	N	N	1	5/8/94	Goar/Nova		2%				040-94-051
2	Room 204	36.5	floor tile adhesive (sample 36)	M		Pos	234	SF	N	N	1	5/8/94	Goar/Nova		7%				040-94-051
2	Room 204	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 206	45	12"x12" pegboard CT	M	ND		192	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 206	45.5	ceiling tile adhesive (sample 45)	M		Pos	192	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 206	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 206	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 207	45	12"x12" pegboard CT	M	ND		204	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 207	45.5	ceiling tile adhesive (sample 45)	M		Pos	204	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 207	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 207	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 208	45	12"x12" pegboard CT	M	ND		285	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 208	45.5	ceiling tile adhesive (sample 45)	M		Pos	285	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 208	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 208	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 209	45	12"x12" pegboard CT	M	ND		285	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 209	45.5	ceiling tile adhesive (sample 45)	M		Pos	285	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 209	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 209	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 210	45	12"x12" pegboard CT	M	ND		256	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 210	45.5	ceiling tile adhesive (sample 45)	M		Pos	256	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 210	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 210	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 211	45	12"x12" pegboard CT	M	ND		284	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 211	45.5	ceiling tile adhesive (sample 45)	M		Pos	284	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051

2	Room 211	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 211	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 212	45	12"x12" pegboard CT	M	ND		256	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 212	45.5	ceiling tile adhesive (sample 45)	M		Pos	256	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 212	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 212	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 213	45	12"x12" pegboard CT	M	ND		130	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 213	45.5	ceiling tile adhesive (sample 45)	M		Pos	130	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 213	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 213	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 214	45	12"x12" pegboard CT	M	ND		102	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 214	45.5	ceiling tile adhesive (sample 45)	M		Pos	102	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 214	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 214	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 215	30	baseboard adhesive	M	ND			LF	N	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 215	30.5	hard brown baseboard	M		Pos	50	LF	N	N	1	5/8/94	Goar/Nova		12%				040-94-051
2	Room 215	33	9"x9" red & brown FT	M		Pos	153	SF	N	N	1	5/8/94	Goar/Nova		12%				040-94-051
2	Room 215	33.5	floor tile adhesive (sample 33)	M		Pos	153	SF	N	N	1	5/8/94	Goar/Nova		3%				040-94-051
2	Room 215	45	12"x12" pegboard CT	M	ND		153	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 215	45.5	ceiling tile adhesive (sample 45)	M		Pos	153	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
2	Room 215	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 215	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 215	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	6	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
2	Room 216	40	decorative plaster	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
2	Room 216	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Corridor	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Corridor	35	12"x12" white w/tan FT	M		Pos	792	SF	N	N	1	5/8/94	Goar/Nova		10%				040-94-051
3	Corridor	35.5	floor tile adhesive (sample 35)	M		Pos	792	SF	N	N	1	5/8/94	Goar/Nova		3%				040-94-051
3	Corridor	45	12"x12" pegboard CT	M	ND		700	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Corridor	45.5	ceiling tile adhesive (sample 45)	M		Pos	700	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Corridor	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

3	Corridor	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Hall	29	sheetrock & taping comp.	M	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Hall	45	12"x12" pegboard CT	M	ND		170	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Hall	45.5	ceiling tile adhesive (sample 45)	M		Pos	170	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Hall	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Hall	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 301	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 301	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 301	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	3	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 302	45	12"x12" pegboard CT	M	ND		135	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 302	45.5	ceiling tile adhesive (sample 45)	M		Pos	135	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 302	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 302	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 302	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 303	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 303	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 303	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 303	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 303	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 304	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 304	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 304	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 304	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 304	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 305	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 305	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 305	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 305	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 307	45	12"x12" pegboard CT	M	ND		136	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 307	45.5	ceiling tile adhesive (sample 45)	M		Pos	136	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051

3	Room 307	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 307	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 307	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 308	45	12"x12" pegboard CT	M	ND		136	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 308	45.5	ceiling tile adhesive (sample 45)	M		Pos	136	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 308	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 308	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 308	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 309	45	12"x12" pegboard CT	M	ND		126	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 309	45.5	ceiling tile adhesive (sample 45)	M		Pos	126	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 309	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 309	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 309	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 310	45	12"x12" pegboard CT	M	ND		134	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 310	45.5	ceiling tile adhesive (sample 45)	M		Pos	134	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 310	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 310	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 310	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 311	45	12"x12" pegboard CT	M	ND		134	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 311	45.5	ceiling tile adhesive (sample 45)	M		Pos	134	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 311	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 311	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 311	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 312	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 312	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 312	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 312	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 312	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 313	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 313	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 313	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

3	Room 313	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 313	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	3	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 314	45	12"x12" pegboard CT	M	ND		136	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 314	45.5	ceiling tile adhesive (sample 45)	M		Pos	136	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 314	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 314	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 314	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	L	3	5/8/94	Goar/Nova		5%				040-94-051
3	Room 315	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 315	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 315	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 315	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 315	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 316	45	12"x12" pegboard CT	M	ND		142	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 316	45.5	ceiling tile adhesive (sample 45)	M		Pos	142	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 316	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 316	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 316	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 317	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 317	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 317	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 317	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 317	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 318	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 318	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 318	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 318	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 318	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		5%				040-94-051
3	Room 319	45	12"x12" pegboard CT	M	ND		142	SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 319	45.5	ceiling tile adhesive (sample 45)	M		Pos	142	SF	N	N	1	5/8/94	Goar/Nova		15%				040-94-051
3	Room 319	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051
3	Room 319	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova						040-94-051

3	Room 319	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	3	EA	F	N	2	5/8/94	Goar/Nova		5%					040-94-051
3	Room 320	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 320	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 320	R1	<4" white fibrous PI (3/27/90)	T		Pos	6	LF	F	N	2	5/8/94	Goar/Nova		30%					040-94-051
3	Room 320	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		30%			1%		040-94-051
3	Room 320	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 320	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 321	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 321	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 321	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 321	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 322	45	12"x12" pegboard CT	M	ND		172	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 322	45.5	ceiling tile adhesive (sample 45)	M		Pos	172	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 322	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 322	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 323	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 323	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 323	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 323	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 324	45	12"x12" pegboard CT	M	ND		134	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 324	45.5	ceiling tile adhesive (sample 45)	M		Pos	134	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 324	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 324	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 325	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 325	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 325	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 325	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 326	45	12"x12" pegboard CT	M	ND		116	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 326	45.5	ceiling tile adhesive (sample 45)	M		Pos	116	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 326	R1	<4" white fibrous PI (3/27/90)	T		Pos	5	LF	F	N	2	5/8/94	Goar/Nova		30%					040-94-051

3	Room 326	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	1	EA	F	N	2	5/8/94	Goar/Nova		30%			1%		040-94-051
3	Room 326	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 326	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 327	57	asbestos wiring	M		Pos	40	LF	N	N	1	5/8/94	Goar/Nova		55%					040-94-051
3	Room 327	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 327	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 328	45	12"x12" pegboard CT	M	ND		140	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 328	45.5	ceiling tile adhesive (sample 45)	M		Pos	140	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 328	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 328	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 329	45	12"x12" pegboard CT	M	ND		134	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 329	45.5	ceiling tile adhesive (sample 45)	M		Pos	134	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 329	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 329	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 330	45	12"x12" pegboard CT	M	ND		152	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 330	45.5	ceiling tile adhesive (sample 45)	M		Pos	152	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 330	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 330	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 331	45	12"x12" pegboard CT	M	ND		144	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 331	45.5	ceiling tile adhesive (sample 45)	M		Pos	144	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 331	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 331	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 332	45	12"x12" pegboard CT	M	ND		162	SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 332	45.5	ceiling tile adhesive (sample 45)	M		Pos	162	SF	N	N	1	5/8/94	Goar/Nova		15%					040-94-051
3	Room 332	R1	<4" white fibrous PI (3/27/90)	T		Pos	10	LF	F	N	2	5/8/94	Goar/Nova		30%					040-94-051
3	Room 332	R2	<4" PFI on white fibrous (12/7/90)	T		Pos	2	EA	F	N	2	5/8/94	Goar/Nova		30%			1%		040-94-051
3	Room 332	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 332	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 333	R24	ceiling plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
3	Room 333	R25	wall plaster (4/4/90)	S	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051

3	Room 333	R9	<4" fibrous PFI on FG (12/11/90)	T		Pos	12	EA	F	N	2	5/8/94	Goar/Nova		5%					040-94-051
4	Attic	27	clay tile mortar	M	ND			SF	F	N	0	5/8/94	Goar/Nova							040-94-051
4	Attic	28	yellow brick mortar	M	ND			SF	N	N	0	5/8/94	Goar/Nova							040-94-051
4	Attic	50	canvass vibration joint	M	ND		12	EA	N	N	0	5/8/94	Goar/Nova							040-94-051