

Flr	Location	Samp#	Description	Code	N.D.	Pos	Quan	Unit	Fri	Cond	Rate	Samp Date	Survey	Amos	Chrys	Croc	Trem	Actin	Anth	Project #
SB	Hallway	2	Concrete Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	Hallway	6	Column Cement	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	Hallway	7	Sheetrock Mud	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	Hallway	75	2x4 C.T. lengthwise fissures & holes	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	N.E. Stairwe	1	Wall Plaster	M	ND		0				0	7/6/92	Petersen/Leahy							044-92-065
SB	N.E. Stairwe	2	Concrete Block Mortar	M	ND		0				0	7/6/92	Petersen/Leahy							044-92-065
SB	S20	2	Concrete Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20	4	Clay Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20	6	Column Cement	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20	12	Fill Putty	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20	14	<4" GFPI on FG line	T	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20	15	Small Brick Mortar	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20A	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20A	76	1x1 CT w/random fissures	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20A	176	CT Adhesive (sample 76)	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20B	16	1x1 FT Cream w/wht & blue	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20B	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20B	76	1x1 CT w/random fissures	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20B	176	CT Adhesive (sample 76)	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20C	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20C	76	1x1 CT w/random fissures	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S20C	176	CT Adhesive (sample 76)	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S50	2	Concrete Block Mortar	M	ND		0				0	7/6/92	Petersen/Leahy							044-92-065
SB	S50	6	Column Cement	M	ND		0				0	7/6/92	Petersen/Leahy							044-92-065
SB	S50	7	Sheetrock Mud	M	ND		0				0	7/6/92	Petersen/Leahy							044-92-065
SB	S50	12	Fill Putty	M	ND		0				0	7/6/92	Petersen/Leahy							044-92-065
SB	S65	13	Vibration Cloth	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065
SB	S67	2	Concrete Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy							044-92-065

SB	S67	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
SB	S67	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
SB	S69	2	Concrete Block Mortar	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S69	6	Column Cement	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S69	7	Sheetrock Mud	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S75	2	Concrete Block Mortar	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S75	7	Sheetrock Mud	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S75A	2	Concrete Block Mortar	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S75A	7	Sheetrock Mud	M	ND	0			0	7/6/92	Petersen/Leahy							044-92-065
SB	S90	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
SB	S90A	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
SB	SW Stairwel	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
SB	SW Stairwel	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
SB	SW Stairwel	14	<4" GFPPFI on FG line	T	ND	2		F	N	0	6/22/92	Petersen/Leahy						044-92-065
SB	SW Stairwel	15	Small Brick Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	10	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	10	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	18	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	18	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	18	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	18	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	18	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	19	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	19	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	19	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	19	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065

B	25	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	40	Interior Duct Insulation	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	41	1x1 FT brn w/red & wht	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	78	2x4 CT random fissures&numerous	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	79	2x4 CT random holes & fissures	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	80	2x4 CT random fissures & pinholes	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25	141	FT mastic (sample 41)		ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	38	1x1 FT wht w/tan,crm&gry	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	78	2x4 CT random fissures&numerous	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	50	138	FT Mastic (sample 38)	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10A	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10A	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10A	13	Vibration Cloth	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	43	<4" Repaired WFPFI	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	143	<4" Repaired WFPFI on WFPI	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	243	4"-8" Repaired WFPFI	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10B	343	4"-8" Repaired WFPFI on WFPI	T	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10C	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10C	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	10C	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25A	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065
B	25A	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy						044-92-065

B	25A	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25A	78	2x4 CT random fissures&numerous	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25A	80	2x4 CT random fissures & pinholes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25B	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25B	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25B	75	2x4 C.T. lengthwise fissures & holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25B	78	2x4 CT random fissures&numerous	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	13	Vibration Cloth	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	14	<4" GFPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	43	<4" Repaired WPFI	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	44	Duct Gasket	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	45	Door Insulation	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25C	81	Ceiling Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25D	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25D	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25D	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	25D	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50A	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50A	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50A	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50A	14	<4" GFPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50A	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50A	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50B	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50C	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50C	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50C	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50C	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
B	50C	78	2x4 CT random fissures&numerous	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065

B	50D	2	Concrete Block Mortar	M	ND		0			0	00/00/00							044-92-065
B	50D	24	Baseboard Adhesive	M	ND		0			0	00/00/00							044-92-065
B	50D	40	Interior Duct Insulation	T	ND		0			0	6/22/92	Petersen/Leahy						044-92-065
B	50D	74	2x4 CT random fissure&holes	M	ND		0			0	00/00/00							044-92-065
	Elevator Penthouse		Elevator Brake Pads	M		Pos	2	EA	N	L	2	6/22/92	Petersen/Leahy					044-92-065
	Elevator Per	4	Clay Block Mortar	M	ND						0	6/22/92	Petersen/Leahy					044-92-065
	N.E. Stairwe	1	Wall Plaster	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
	N.E. Stairwe	2	Concrete Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
	Roof	73	Tar Roofing Material	M	ND						0	6/22/92	Petersen/Leahy					044-92-065
1	100	1	Wall Plaster	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	7	Sheetrock Mud	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	14	<4" GFPI on FG line	T	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	74	2x4 CT random fissure&holes	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	74	2x4 CT random fissure&holes	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	75	2x4 C.T. lengthwise fissures & holes	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	100	78	2x4 CT random fissures&numerous	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	105	7	Sheetrock Mud	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	105	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	105	74	2x4 CT random fissure&holes	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	110	7	Sheetrock Mud	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	110	14	<4" GFPI on FG line	T	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	110	24	Baseboard Adhesive	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	110	74	2x4 CT random fissure&holes	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	110	78	2x4 CT random fissures&numerous	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	120	2	Concrete Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	120	4	Clay Block Mortar	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	120	6	Column Cement	M	ND		0				0	6/22/92	Petersen/Leahy					044-92-065
1	120	14	<4" GFPI on FG line	T	ND		0				0	6/22/92	Petersen/Leahy					044-92-065

1	100A	2	Concrete Block Mortar	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100A	7	Sheetrock Mud	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100A	24	Baseboard Adhesive	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100A	74	2x4 CT random fissure&holes	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100C	4	Clay Block Mortar	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100C	5	Standard Brick Mortar	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100C	7	Sheetrock Mud	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100D	7	Sheetrock Mud	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100D	14	<4" GFPPFI on FG line	T	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100D	74	2x4 CT random fissure&holes	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	1	Wall Plaster	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	2	Concrete Block Mortar	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	6	Column Cement	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	7	Sheetrock Mud	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	14	<4" GFPPFI on FG line	T	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	24	Baseboard Adhesive	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100E	74	2x4 CT random fissure&holes	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100F	2	Concrete Block Mortar	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100F	7	Sheetrock Mud	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100F	14	<4" GFPPFI on FG line	T	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100F	24	Baseboard Adhesive	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100F	74	2x4 CT random fissure&holes	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100H	1	Wall Plaster	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100H	2	Concrete Block Mortar	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100K	1	Wall Plaster	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100K	1	Wall Plaster	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100K	24	Baseboard Adhesive	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100K	24	Baseboard Adhesive	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100K	74	2x4 CT random fissure&holes	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065
1	100K	74	2x4 CT random fissure&holes	M	ND	0	0	6/22/92	Petersen/Leahy	044-92-065

1	100K	78	2x4 CT random fissures&numerous	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100M	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100M	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100M	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100M	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100N	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100N	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	100N	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	110B	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	110B	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	110B	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	110B	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	110B	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	110B	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	120A	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	120A	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	120A	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	120A	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	120A	154	FT Mastic (sample 54)	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	NE Entrance	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	NE Entrance	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	NE Entrance	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	S.W. Stairwe	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	S.W. Stairwe	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	S.W. Stairwe	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	South Hallwa	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	South Hallwa	7	Sheetrock Mud	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	South Hallwa	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	South Hallwa	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
1	South Hallwa	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065

2	200	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	200	6	Column Cement	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	200	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	215	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	215	5	Standard Brick Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	215	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	215	158	FT Mastic (sample 58)	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	217	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	217	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	218	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	218	14	<4" GFPI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	218	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	219	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	219	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	219	76	1x1 CT w/random fissures	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	220	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	220	60	4"-8" RFPI	T	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	220	61	4"-8" WFPFI on RFPI	T	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	220	62	9"-14" RFPI	T	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	220	63	9"-14" WFPFI on RFPI	T	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	221	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	221	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	221	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	228	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	228	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	228	5	Standard Brick Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	240	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065
2	240	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy									044-92-065

2	240	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	240	81	Ceiling Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250	76	1x1 CT w/random fissures	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	260	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200A	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200A	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200B	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200B	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200C	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200C	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200D	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200E	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200E	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200E	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	200E	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	240A	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	240A	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	240A	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250A	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250A	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250A	76	1x1 CT w/random fissures	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250B	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250B	14	<4" GFPPFI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250B	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065
2	250B	83	2x2 CT rough texture	M	ND	0			0	6/22/92	Petersen/Leahy							044-92-065

2	South Entry	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
2	South Entry	4	Clay Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
2	South Entry	14	<4" GFPI on FG line	T	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
2	South Entry	24	Baseboard Adhesive	M	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
2	South Entry	74	2x4 CT random fissure&holes	M	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
2	SW Stairwel	1	Wall Plaster	M	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
2	SW Stairwel	2	Concrete Block Mortar	M	ND	0			0	6/22/92	Petersen/Leahy								044-92-065
3	301	4	Clay Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	7	Sheetrock Mud	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	24	Baseboard Adhesive	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	67	Brown Floor Sheeting	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	69	Red&Brn Floor Sheeting	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	71	Brn&Gold Floor Sheeting	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	167	Floor Adhesive (#67)	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	169	Floor Adhesive (#69)	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	301	171	Floor Adhesive (#71)	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	302	4	Clay Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	302	7	Sheetrock Mud	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	302	24	Baseboard Adhesive	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	303	2	Concrete Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	303	4	Clay Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	303	6	Column Cement	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	304	2	Concrete Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	304	4	Clay Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	304	5	Standard Brick Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	305	4	Clay Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	306	2	Concrete Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	306	4	Clay Block Mortar	M	ND				0	7/6/92	Petersen/Leahy								044-92-065
3	306	14	<4" GFPI on FG line	T	ND				0	7/6/92	Petersen/Leahy								044-92-065

3	307	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	307	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	307	14	<4" GFPPFI on FG line	T	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	307	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	307	74	2x4 CT random fissure&holes	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	69	Red&Brn Floor Sheeting	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	76	1x1 CT w/random fissures	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	169	Floor Adhesive (#69)	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	301A	176	CT Adhesive (sample 76)	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302A	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	13	Vibration Cloth	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	65	1x1 FT grey w/wht & blk		ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	74	2x4 CT random fissure&holes	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	302B	165	FT Mastic (sample 65)		ND					0	7/6/92	Petersen/Leahy							044-92-065
3	303A	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	303B	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	303B	65	1x1 FT grey w/wht & blk		ND					0	7/6/92	Petersen/Leahy							044-92-065
3	303B	165	FT Mastic (sample 65)		ND					0	7/6/92	Petersen/Leahy							044-92-065
3	306A	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	306A	13	Vibration Cloth	M	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	306A	14	<4" GFPPFI on FG line	T	ND					0	7/6/92	Petersen/Leahy							044-92-065
3	306B	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy							044-92-065

3	306C	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	306C	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	306C	14	<4" GFPPFI on FG line	T	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	306C	67	Brown Floor Sheeting	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	306C	167	Floor Adhesive (#67)	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307A	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307A	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307A	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307A	74	2x4 CT random fissure&holes	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307A	78	2x4 CT random fissures&numerous	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307B	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307B	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307B	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307B	78	2x4 CT random fissures&numerous	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307C	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307C	14	<4" GFPPFI on FG line	T	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307C	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	307C	74	2x4 CT random fissure&holes	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	SW Stairwel	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	SW Stairwel	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
3	SW Stairwel	14	<4" GFPPFI on FG line	T	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	400	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	400	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	400	5	Standard Brick Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403	5	Standard Brick Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	405	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	409	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065

4	409	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	410	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	410	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	410	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	410	67	Brown Floor Sheeting	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	410	167	Floor Adhesive (#67)	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	411	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	411	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	413	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	413	24	Baseboard Adhesive	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403A	7	Sheetrock Mud	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403A	67	Brown Floor Sheeting	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403A	76	1x1 CT w/random fissures	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403A	167	Floor Adhesive (#67)	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403A	176	CT Adhesive (sample 76)	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403B	4	Clay Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	403B	5	Standard Brick Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	410A	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	SW Stairwel	1	Wall Plaster	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	SW Stairwel	2	Concrete Block Mortar	M	ND					0	7/6/92	Petersen/Leahy						044-92-065
4	SW Stairwel	14	<4" GFPI on FG line	T	ND					0	7/6/92	Petersen/Leahy						044-92-065